
10
TAILINGS
12
ADJUST MOISTURE
14
AERATE SURFACE LAYER
16
ADJUST PH
18
ADJUST MOISTURE
OXIDATION
20
22
REMOVE SURFACE LAYER
24
WATER
SLURRY
26
30
28
SEPARATION
SOLIDS
WASHING
SOLUTION
32
34
COPPER EXTRACTION
TAILINGS DAM